

Appendix A: Photos



Terwilliger Fire 2018 - BAER - Recreation

^Terwilliger Hot Springs, with recent burned log sluffing into lower pool area



Terwilliger Fire 2018 - BAER - Recreation



^Terwilliger Hot Springs, with French drain above upper pool, and imposing hazards



Terwilliger retaining wall and threatened tread at entrance to Rider Creek Trail 3319 that accesses hot spring area



Fire burned out trail surface and sub-surface retaining materials, posing a risk of property loss.

Terwilliger Fire 2018 - BAER - Recreation



^ French Pete Trail v

Terwilliger Fire 2018 - BAER - Recreation



^ Charred sheet metal covers the fiberglass vaults at what previously were the Terwilliger Hot Springs Bathrooms

v Exposed liquefied human excrement remains on site, posing a hazardous material exposure risk



Terwilliger Fire 2018 - BAER - Recreation

Appendix B: Sign Examples



WARNING

Entering Burned Area,
Potential Hazards
Include:

Loose Rocks, Falling
Trees and Limbs,
Flash Flooding
and Debris Flows.
Portions of Trail are
Damaged or
Blocked with Debris.

